	Туре	L#	Hits	Search Text
1	BRS	L1	10709	shunt.clm.
2	BŖS	L2	227	1 and (semiconduct\$5) near2 (film layer)
3	BRS	L3	81	1 and (semiconduct\$5) near2 (film layer).clm.
4	BRS	L4	10	3 and (strain stress force pressure).clm.
5	BRS	L5	2	4 and (measur\$5 detect\$5 sens\$5).clm.
6	BRS	L6	77	metal\$5 near2 shunt.clm.
7	BRS	L7	8	6 and (semiconduct\$5) near2 (film layer).clm.
8	BRS	L9	1	8 and (measur\$5 detect\$5 sens\$5).clm.
9	BRS	L10	2	8 and (measur\$5 detect\$5 sens\$5)
10	BRS	L8	3	7 and (strain stress force pressure).clm.
11	BRS	L11	10	"5663507"
12	BRS	L12	0	11 and metal\$5 near2 shunt
13	BRS	L13	468	metal\$5 near2 shunt
14	BRS	L14	61	13 and (semiconduct\$5) near2 (film layer)
15	BRS	L15	27	14 and (strain stress force pressure)
16	BRS [']	L16	22	15 and (measur\$5 detect\$5 sens\$5)
17	BRS	L17	19	16 and (voltage)
18	BRS	L18	20749	(strain stress force pressure) near3 (interface)
19	BRS	L19	1993	(strain stress force pressure) near3 (interface).clm.
20	BRS	L20	1	19 and metal\$5 near2 shunt

	DBs	Time Stamp	Comments	Error Definition	Erro rs
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	•			0
2	USPAT; US-PGPUB; EPO; JPO; DERWENT				0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	• •			0
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	i ' '			0
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	:			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21			О
7	USPAT; US-PGPUB; EPO; JPO; DERWENT				0
8	USPAT; US-PGPUB; EPO; JPO; DERWENT	:			0
9	USPAT; US-PGPUB; EPO; JPO; DERWENT	:			0
10	USPAT; US-PGPUB; EPO; JPO; DERWENT				0
11	USPAT; US-PGPUB; EPO; JPO; DERWENT				0
12	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21 14:51			0
13	USPAT; US-PGPUB; EPO; JPO; DERWENT	;			0
14	USPAT; US-PGPUB; EPO; JPO; DERWENT	· · ·			0
15	USPAT; US-PGPUB; EPO; JPO; DERWENT	· ·			0
16	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21			0
17	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21			0
18	USPAT; US-PGPUB; EPO; JPO; DERWENT				0
19	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21			0
20	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21 14:49			0

	Туре	L#	Hits	Search Text
21	BRS	L21	4	18 and metal\$5 near2 shunt
22	BRS	L22	4	11 and shunt

	DBs	Time Stamp	Comments	Error Definition	Erro rs
21	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21 14:49			0
22	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/21 14:51			0